

Colt Atlantic Services, Inc.

June 26, 2002

Subject: Leachable Chlorides in Colt Sealant Compounds

<u>COMPOUND</u>	<u>LEACHABLE CHLORIDES</u>
F-150	None Detected
A-2	32 ppm
F-150	None Detected
F-250	18 ppm
S-8	41 ppm
S-10	12 ppm
S-11	6 ppm
S-13	None Detected
S-14	5 ppm
S-15	None Detected
S-16	2 ppm
S-17	2 ppm
S-18	6 ppm
S-19	6 ppm
S-20	None Detected
S-21	None Detected

These are generic test results only, every batch is not tested.
Per ASTM D 512-88

P.O. Box 74396 Richmond, VA 23236 24 HR. 804-674-0031 Fax 804-674-1107

Leak Sealing Pipe Freezing Pipe Taps Concrete Repairs Transformer Oil Leak Repairs

Colt Atlantic Services, Inc.

COMPOUND	LEACHABLE CHLORIDES
S-22	None Detected
S-23	None Detected
S-24	None Detected
S-25	22 ppm
S-26	16 ppm
S-28	14 ppm
S-29	None Detected
S-30	None Detected
S-31	7 ppm
S-32	7 ppm
S-33	25 ppm
S-34	4 ppm
S-35	None Detected
S-36	3 ppm
F-49	3 ppm

These are generic test results only, every batch is not tested.
Per ASTM D 512-88

P.O. Box 74396 Richmond, VA 23236 24 HR. 804-674-0031 Fax 804-674-1107

Leak Sealing Pipe Freezing Pipe Taps Concrete Repairs Transformer Oil Leak Repairs