


Bushing Flange Repair



A bushing flange can be repaired without removing or lowering the oil level using Colts drill and tap procedure. In many cases flanges that have a "groove" for the gasket/O-ring to sit in are repaired in a matter of hours using our proven injection process. A proprietary, two-part rubber like sealant is hydraulically injected into the gasket area to seal the leak. This sealant has excellent dielectric properties and has had dissolved gas analysis completed. The Power Services Division of Colt was formed in 2001 and has completed thousands of documented electrical equipment leaks in the United States and Canada.

All repairs are guaranteed for two years.